

# PORT MARINE SAFETY CODE

- Vessels must not lie in the approaches to the harbour to avoid risk of collision and must at all times obey the International Regulations for Preventing Collisions at Sea.
- Maximum speed in harbour limits is 3 knots.
- Jet Skis (Personal Water Crafts are not permitted within harbour limits.
- Enter / exit the harbour on the starboard side of the channel.
- Berthing / Sailing limits must be assessed by the Harbour Master with due regard to: length of vessel, draft, beam, present weather, weather forecast, number of times vessel / Master has been in the port, availability of berthing space.
- Harbour Master's decision is final on limits to entry.
- Ensure safe access across vessels, especially those with shelter decks.
- No berthing at Fish Market or Ice Plant berths.
- Ensure that up to date details concerning the vessel, including contact names and numbers are with the Harbour Master.
- No dumping of any waste in harbour - all galley waste to be placed in bins provided.
- All waste oil to be collected in drums and transferred to the tank in the harbour yard.
- Vessel owners are responsible for disposing of redundant gear in a proper manner.
- Minimum of 2 competent persons to refuel vessels. No refuelling at fish market berths.
- Mooring procedures: - moor only to bollards ashore: no mooring to ladders or other vessels
  - always re-moor outside vessels; do not cast vessels adrift.
- Only the appropriate navigational lights/shapes should be exhibited.